




 JULY 2016  
**PRICE LIST**



 MVPGROUPCORP.COM  
 SALES@MVPGROUPCORP.COM

 **514-737-9701**

TOLL FREE: **888-275-4538**



# JULY 2016 PRICE LIST



SRF-25/25      SRF-40/50      SRF-75/80

### 2 YEAR TANK WARRANTY

Full unit replacement. See conditions on back.



SR-4-24      SR-6-36      SR-10-60



SRSP-18



SRCB-36



SRRB-36

## GAS FRYERS

### SRF-25/25

(4) 30,000 BTU burners, 2 x 25 lbs. capacity, s/s, galvanized back, 6" adjustable legs

### SRF-35/40

(3) 30,000 BTU burners, 35-40 lbs. capacity, s/s, galvanized sides & back, 6" adjustable legs

### SRF-40/50

(3) 38,000 BTU burners, 40-50 lbs. capacity, s/s, galvanized back, 6" adjustable legs

### SRF-SC-40/50

(4) 30,000 BTU burners, 40-50 lbs. capacity, all s/s cabinet, 6" adjustable legs

### SRF-75/80

(5) 30,000 BTU burners, 75-80 lbs. capacity, s/s, galvanized sides & back, 6" adjustable legs

### SRF-SC-75/80

(5) 30,000 BTU burners, 75-80 lbs. capacity, all s/s cabinet, 6" adjustable legs

BTU	LIST PRICE	SHIP WT.
120,000	\$3,860	190 lbs
90,000	\$1,850	150 lbs
114,000	\$2,200	167 lbs
120,000	\$3,540	158 lbs
150,000	\$3,290	265 lbs
150,000	\$4,060	265 lbs

## GAS RANGES

### SR-4-24

(4) 30,000 BTU heavy duty cast iron burners, 32,000 BTU oven burner, s/s, galvanized back, 6" adjustable legs

### SR-6-36

(6) 30,000 BTU heavy duty cast iron burners, 32,000 BTU oven burner, s/s, galvanized back, 6" adjustable legs

### SR-10-60

(10) 30,000 BTU heavy duty cast iron burners, 32,000 BTU oven burner, s/s, galvanized back, 6" adjustable legs

152,000	\$3,700	309 lbs
212,000	\$3,900	410 lbs
364,000	\$7,390	725 lbs

## STOCK POT RANGE

### SRSP-18

18" wide, (1) heavy duty cast iron burner, manual control with pilot, s/s exterior, 6" adjustable legs

100,000	\$1,500	128 lbs
---------	---------	---------

## CHAR ROCK BROILERS

### SRCB-24

24" wide, (4) steel "fluted" burners, cast iron grates, manual control, s/s exterior, crumb tray

### SRCB-36

36" wide, (6) steel "fluted" burners, cast iron grates, manual control, s/s exterior, crumb tray

### SRCB-48

48" wide, (8) steel "fluted" burners, cast iron grates, manual control, s/s exterior, crumb tray

64,000	\$2,300	170 lbs
96,000	\$3,090	229 lbs
128,000	\$4,050	289 lbs

## RADIANT BROILERS

### SRRB-12

12" wide, (1) steel "fluted" burner, cast iron grates, manual control, s/s exterior, crumb tray

### SRRB-24

24" wide, (4) steel "fluted" burners, cast iron grates, manual control, s/s exterior, crumb tray

### SRRB-36

36" wide, (6) steel "fluted" burners, cast iron grates, manual control, s/s exterior, crumb tray

### SRRB-48

48" wide, (8) steel "fluted" burners, cast iron grates, manual control, s/s exterior, crumb tray

16,000	\$1,620	110 lbs
64,000	\$2,460	170 lbs
96,000	\$3,370	229 lbs
128,000	\$4,440	288 lbs



# JULY 2016 PRICE LIST



SRMG-36



SRTG-24



SRHP-4-24



SRS-24



SRCM-24

## MANUAL GRIDDLES

		BTU	LIST PRICE	SHIP WT.
<b>SRMG-12</b>	12" wide, 5/8" thick steel griddle plate, (1) "U" shaped burner, manual control, s/s exterior, 4" grease trough	23,000	\$1,580	125 lbs
<b>SRMG-24</b>	24" wide, 3/4" thick steel griddle plate, (2) "U" shaped burners, manual controls, s/s exterior, 4" grease trough	46,000	\$2,360	174 lbs
<b>SRMG-36</b>	36" wide, 3/4" thick steel griddle plate, (3) "U" shaped burners, manual controls, s/s exterior, 4" grease trough	69,000	\$3,070	242 lbs
<b>SRMG-48</b>	48" wide, 3/4" thick steel griddle plate, (4) "U" shaped burners, manual controls, s/s exterior, 4" grease trough	92,000	\$4,120	304 lbs

## THERMOSTAT GRIDDLES

<b>SRTG-24</b>	24" wide, 1" thick steel griddle plate, (2) "U" shaped burners, thermostat controls, s/s exterior, 4" grease trough	60,000	\$3,250	174 lbs
<b>SRTG-36</b>	36" wide, 1" thick steel griddle plate, (3) "U" shaped burners, thermostat controls, s/s exterior, 4" grease trough	90,000	\$4,790	242 lbs
<b>SRTG-48</b>	48" wide, 1" thick steel griddle plate, (4) "U" shaped burners, thermostat controls, s/s exterior, 4" grease trough	120,000	\$5,620	304 lbs
<b>SRTG-60</b>	60" wide, 1" thick steel griddle plate, (5) "U" shaped burners, thermostat controls, s/s exterior, 4" grease trough	150,000	\$7,460	372 lbs

## HOT PLATES

<b>SRHP-2-12</b>	12" wide, (2) 30,000 BTU lift top piece cast iron burners, manual control w/ pilot ignition, s/s exterior	60,000	\$1,200	93 lbs
<b>SRHP-4-24</b>	24" wide, (4) 30,000 BTU lift top piece cast iron burners, manual control w/ pilot ignition, s/s exterior	120,000	\$1,870	152 lbs
<b>SRHP-6-36</b>	36" wide, (6) 30,000 BTU lift top piece cast iron burners, manual control w/ pilot ignition, s/s exterior	180,000	\$2,740	214 lbs

## SALAMANDERS

<b>SRS-24</b>	24" wide, (1) infrared burner, manual control with pilot, chrome plated rack assembly, 4 rack adjustable positions, s/s, wall mount kit included	20,000	\$2,950	99 lbs
<b>SRS-36</b>	36" wide, (2) infrared burners, manual control with pilot, chrome plated rack assembly, 4 rack adjustable positions, s/s, wall mount kit included	40,000	\$3,800	135 lbs

## CHEESEMELTERS

<b>SRCM-24</b>	24" wide, (1) infrared tile burner, manual control with pilot ignition, (1) rack with three adjustable rack positions, s/s exterior, wall mount kit included	20,000	\$1,620	68 lbs
<b>SRCM-36</b>	36" wide, (2) infrared tile burners, manual controls with pilot ignition, (1) rack with three adjustable rack positions, s/s exterior, wall mount kit included	40,000	\$2,190	106 lbs

## ACCESSORIES

### EQUIPMENT STANDS

ES-3024	\$310	ES-3060	\$550
ES-3036	\$380	ES-3072	\$620
ES-3048	\$460		

### RANGE MOUNT KITS

RMK-24	\$190
RMK-36	\$260

### FRYER ACCESSORIES

Basket	\$80
Tank Cover (3 & 4 tube)	\$840
Tank Cover (5 tube)	\$960
Cleaning Tool Set	\$160
Joining Strip	\$35

### OTHER

Casters (Set of 4)	\$180
Casters (Set of 6)	\$220
Oven Rack 24"	\$150
Oven Rack 36"	\$180
4" Legs (For counter-top units)	\$25 each



## TERMS & CONDITIONS

**SHIPMENT:** F.O.B. Warehouse – Montreal, QC or Mississauga, ON

**SHIPPING CLASS:** 85

**TERMS:** 3% CIA or NET 30, on approved accounts only.

**RETURNS:** Return shipments MUST have written authorization prior to return; and shall be subject to a re-stocking charge of 35%.

**PRICING:** All prices shown are list. MVP GROUP CORP. assumes no responsibility for carrier rates or charges, nor will it make any allowance from pricing for freight charges. Prices are subject to change without notice, and as exist at time of shipment.

**DAMAGES:** Claims for damages must be made by the consignee directly with the carrier. MVP GROUP CORP. assumes no responsibility for damages while in transit. MERCHANDISE MUST BE INSPECTED PRIOR TO CARRIER LEAVING YOUR PREMISES.

**DELIVERY:** Whenever feasible, a preferred carrier will be used, however we reserve the right to ship via any responsible carrier. Rate charges or discrepancies are between carrier and consignee.

The manufacturer reserves the right to alter design and specifications without notice. These conditions are the terms upon which an order is accepted and constitutes an Agreement of Sale. MVP GROUP CORP. assumes no responsibility for the product when misused, abused or incorrectly applied. In any such instance, the warranty becomes null and void.

## MANUFACTURERS LIMITED WARRANTY

MVP Group Corporation, (Sierra Range, hereby referred to as "Sierra"), warrants all new cooking equipment bearing the name "SIERRA" and installed within the continental United States of America\* or Canada to be free from defects in material or workmanship, under normal and regular usage and operation for a period of one (1) year following the date of original installation, but in no event can exceed eighteen (18) months from the date of shipment from the factory, unless specified otherwise.

If a defect in material(s) or workmanship is detected, or found to exist within the stated period above, MVP Group Corporation, at its sole discretion, shall either repair or replace any original part which has proven to fail within the machine, providing that the equipment has not been altered or tampered with in any manner, has been installed correctly as per the owner's manual, and has been maintained and operated in complete accordance with this manual.

The labor cost to repair or replace any part proven to be defective, as per above clause(s), shall be covered by MVP Group Corporation, within the United States of America\* or Canada; provided that: prior authorization for this labor was pre-approved by MVP Group Corporation, the service work was performed by an authorized MVP Group Corporation service agent; and that this agent installed an original and genuine Sierra part in the machine. Any repair work performed by a non-authorized service agent remains the sole responsibility of the user, and MVP Group Corporation will not be held responsible. The installation of any generic part will not be valid; and therefore voids this warranty. All authorized labor coverage shall be limited to regular hourly rates only. Any supplemental hourly rates or charges, such as weekends or emergency premiums, remain the responsibility of the user.

MVP Group Corporation (Sierra) hereby states that: warranty travel time shall be limited to, and without exception, a round-trip total of two (2) hours OR mileage up to a maximum of one hundred (100) km round-trip. Any charges exceeding those stated herein must have prior authorization by the factory.

A special warranty covers the SRF series. These units carry the regular one (1) year parts and labor plus an additional fry tank warranty to the original end user only; if the fry tank leaks within the first two (2) years of operation due to a manufacturing defect, as confirmed by an MVP Group Corporation authorized service agent, MVP Group Corporation shall replace the fryer in its entirety. Any associated freight and/or installation charges shall not be included with the replacement.

**Exceptions to above warranty are:** (A) Damages resulting from shipping, handling or abuse. (B) Incorrect installation and/or connections. (C) Adjustments or calibration of any thermostats or timers. (D) Faults due to lack of regular maintenance or cleaning of any internal or external part(s). (E) Replacement of any wearable items such as: baskets, grills, knobs, etc. (F) Excessive soot accumulation due to poor gas conditions. (G) Poor results due to: excessive or inadequate temperature(s) or gas pressure conditions (H) Failure to follow manual's lighting instructions, maintenance and/or usage.

MVP GROUP CORPORATION STATES THAT THERE ARE NO OTHER WARRANTIES, EXPRESSED OR IMPLIED, THAT ARE NOT SET FORTH HEREIN. MVP GROUP CORPORATION SHALL ASSUME NO OTHER RESPONSIBILITY, EITHER DIRECT OR NON-DIRECT, OR BE LIABLE FOR ANY OTHER ADDITIONAL LOSS OR DAMAGE, WHETHER DIRECT OR CONSEQUENTIAL, AS A RESULT OF ITS EQUIPMENT.

\*Some exceptions apply.

The manufacturer reserves the right to alter design and specifications without notice.



🌐 [MVPGROUPCORP.COM](http://MVPGROUPCORP.COM)  
✉ [SALES@MVPGROUPCORP.COM](mailto:SALES@MVPGROUPCORP.COM)

🇨🇦 **514-737-9701**  
TOLL FREE: **888-275-4538**